

Office
Test
\$25.00

RD Water Lab, LLC

3700 S. Russell St. 120 - #1 Missoula, MT 59801

P.O. Box 5064

Phone: (406) 721-8179

Missoula, MT 59806

Bacteriological Analysis of Drinking Water

Customer: King Ranch Subdivision II & III Person to receive report: _____
 Address: Frenchtown PWSID #: MT0004158 Name: King Ranch Subdivision
 Date: 7-2-24 Time: 12:15 Address: PO Box 118
 Contact: Charles I Weihe Phone: 5806 City: Frenchtown State: MT Zip: 59834
 Point water supply: Well Sample: 406-531-3243 Phone results Fax results
 Point of use: N/A Home use Public use

Lab #	Lab #	ENTER SAMPLE SITE	Code	Notes
RT	2407-066	X1	17771 Wildgoose DS001 SP001	Coliform Absent E. coli Absent
				Coliform Absent E. coli Absent
				Coliform Absent E. coli Absent
				Coliform Absent E. coli Absent
				Coliform Absent E. coli Absent

Received: 7-2-24
 Reported: 7-3-24
 Analyst: UG
 Satisfactory at this time
 Contaminated
 Water supply should be disinfected and retested before being used as drinking or household water.
B

1580
0900

SAMPLES MUST ARRIVE WITHIN 30 HOURS OF COLLECTION! Keep Sample Cool, NOT Frozen

Samples may be dropped off on either Monday - Friday 9am - 4pm,
or mailed Monday - Thursday to P.O. Box 5064 • Missoula, MT 59806