

RD Water Lab, LLC

ColiAlert
Test
\$25.00

3700 S. Russell St. 120 - #1, Missoula, MT 59801

P.O. Box 5064

Phone: (406) 721-8179

Missoula, MT 59806

Bacteriological Analysis of Drinking Water

Blue Ribbon Water Testing
406-531-1176

Name of business: King Ranch Subdivision II & III Person to receive report:
City: Frenchtown PWSID #: MT0004158 Name: King Ranch Subdivision
Date collected: 11-4-24 Time: 1:31 PM Address: PO Box 118
Sample collector: Charles I Weihe Cert #: 5806 City: Frenchtown St.: MT Zip: 59834
Type of water supply: Well Phone: 406-531-3243 Phone results *If long distance add \$1.00
Chlorine residual: N/A Fax: Fax results

| Test Type | Lab # | ENTER SAMPLE SITE | | | | | |
|-----------|----------|-------------------|------------------------|--|---------------------------------------|---|--|
| RT | 2411-044 | X2 | 17435 | Phase II | DS001 | <input checked="" type="checkbox"/> Coliform Absent | |
| | | | St Andrews | | SP001 | <input type="checkbox"/> Coliform present E. coli <input checked="" type="checkbox"/> Absent <input type="checkbox"/> Present | |
| | | | Coliform Absent | | | | <input type="checkbox"/> Coliform Absent |
| | | | | | | | <input type="checkbox"/> Coliform present E. coli <input type="checkbox"/> Absent <input type="checkbox"/> Present |
| | | | | | | | <input type="checkbox"/> Coliform Absent |
| | | | | <input type="checkbox"/> Coliform present E. coli <input type="checkbox"/> Absent <input type="checkbox"/> Present | <input type="checkbox"/> Contaminated | | |
| | | | | <input type="checkbox"/> Coliform Absent | Water supply should | | |
| | | | | <input type="checkbox"/> Coliform present E. coli <input type="checkbox"/> Absent <input type="checkbox"/> Present | be disinfected and | | |
| | | | | <input type="checkbox"/> Coliform Absent | retested before being | | |
| | | | | <input type="checkbox"/> Coliform present E. coli <input type="checkbox"/> Absent <input type="checkbox"/> Present | used as drinking or | | |
| | | | | <input type="checkbox"/> Coliform Absent | household water. | | |
| | | | | <input type="checkbox"/> Coliform present E. coli <input type="checkbox"/> Absent <input type="checkbox"/> Present | B | | |

Received: ¹⁴⁵⁰ 11-4-24
Reported: 11-5-24
Analyst: LG
 Satisfactory at this time.
 Contaminated
Water supply should be disinfected and retested before being used as drinking or household water.
B

1530
0930

SAMPLES MUST ARRIVE WITHIN 30 HOURS OF COLLECTION! Keep Sample Cool, NOT frozen

Samples may be dropped off in the office Monday - Friday 9am - 4pm,
or mailed Monday - Thursday PM to P.O. Box 5064 • Missoula, MT 59806